

BRIDGES

During the progress of the convoy, there were damaged or destroyed a total of eighty-eight mostly wooden highway bridges and culverts, all of which had to be repaired or rebuilt by the convoy personnel, before the expedition could proceed. It was practically impossible to determine the stability of a bridge thru pre-inspection, due to the dried-out condition of its timbers. Even some of the bridges reinforced by the convoy engineers collapsed during use.

